

IP1980 - Transcatheter aortic valve implantation for native aortic valve regurgitation

The mandated classifications (OPCS-4 or ICD-10) provide a method to collect and aggregate data to allow accurate and consistent data analysis.

Procedure:

OPCS-4 code(s):

K26.- Plastic repair of aortic valve

Y79.- Approach to organ through artery

Y53.- Approach to organ under image control

Or

Y68.- Other approach to organ under image control

Plus

U20.2 Transoesophageal echocardiography (if transoesophageal echocardiography is used)

Plus

K63 Contrast radiology of heart (if angiography is performed)

And

Y53.4 Approach to organ under fluoroscopic control

Diagnosis or health condition:

ICD-10 code(s):

I35.1 Aortic (valve) insufficiency

Clinical coding recommendations for NICE guidance

For each published interventional procedure guidance, we work with NHS England to provide relevant clinical coding information.

The mandated classifications (OPCS-4 or ICD-10) provide a method to collect and aggregate data to allow accurate and consistent data analysis.

NICE and NHS England Terminology and Classifications Delivery Service work collaboratively to ensure the most appropriate OPCS-4 and ICD-10 codes are provided.

NHS England is the national release centre for the UK edition of ICD-10 and OPCS-4. Further Classifications information, see [here](#).